Barndan


ELECTRONIC HIGH SPEED EMBROIDERY MACHINE

BEHJ PARTS LIST

BEHJ ELECTRONIC HIGH SPEED EMBROIDERY MACHINE PARTS LIST


CONTENTS

SEWING HEAD
SEWING HEAD DRIVE 2
ROTARY COLOUR CHANGE HEAD AND TAKE UP MECHANISM… 3
ROTARY COLOUR CHANGE HEAD AND TAKE UP MECHANISM… 4
JUMP STITCH MECHANISM 5
THREAD TENSION ASSEMBLY 6
DRIVE MOTOR AND CLUTCH COMPLETE 7
DRIVE MOTOR AND CLUTCH EXPLODED VIEW 8
ROTARY COLOUR CHANGE SELECTOR ASSEMBLY 9
ROTARY COLOUR CHANGE SELECTOR ASSEMBLY10 (EXPLODED VIEW)
PANTOGRAPH DRIVE MOTOR ASSY AND TIMING BELT11 (BACK/FORWARD MOVEMENT)
PANTOGRAPH TIMING BELT ASSY12 (BACK/FORWARD MOVEMENT)
PANTOGRAPH DRIVE MOTOR ASSY AND TIMING BELT13 (LEFT/RIGHT MOVEMENT)
PANTOGRAPH TIMING BELT ASSY
ELECTRONIC CONTROLS15
UNDER THREAD STOP MOTION(UTSM)ASSY16
LIGHT FITTINGS, THREAD STAND, AND SUPPORTS17



SEWING HEAD (G)

No.	Description
1	2111F SEWING HEAD
2	2121FSEWING HEAD BASE PLATE
3	2512FSEWING HEAD COVER
4	2492FCREAMIC GUIDE (UPPER)
5	2493F·····CREAMIC GUIDE (LOWER)
6	·············ALAN SCREW
7	2513FNEEDLE PLATE
8	NEEDLE PLATE SCREW
9	2255FDUSTPROOF OILER
10	2516FARM SHAFT GEAR COVER
11	RETAINING SCREW FOR G 10
12	2511FREAR BEARING COVER
13	·····GRUB SCREW




SEWING HEAD DRIVE (H)

No.	Description
1	2341F·····TAKE UP LEVER CAM
2	2342F·····LOCATING SCREW
3	2343F······CRANK PIN
4	2344FRETAINING PIN FOR H3
5	··············SCREW FOR H4
Б	GRUB SCREW
7	2214F·····FRONT ARM SHAFT BUSH
В	······GRUB SCREW
9	2211F·····ARM SHAFT
1₽	2216FARM SHAFT CENTRE BUSH
11	2218FCOLLAR
12	GRUB SCREW
13	2212FHELICAL GEAR
14	GRUB SCREW
15	2213F·····BEVEL GEAR (LARGE)
16	······GRUB SCREW
17	2215F·····REAR BUSH
18	2219FCOLLAR
19	GRUB SCREW
20	2245FREAR LOCKING SCREW
21	2246FBEVEL GEAR (SMALL)
22	GRUB SCREW
23	2224FVERTICAL SHAFT BUSH (UPPER)
24	2225FVERTICAL SHAFT
25	2223FBUSH
26	2247FBEVEL GEAR (VERTICAL SHAFT)
27	2248FBEVEL GEAR (HOOK SHAFT)
28	2222F·····HOOK SHAFT BUSH (REAR)
29	2229FCOLLAR
30	GRUB SCREW
31	·····SCREW
32	2227FGREASE COVER (RHS)
33	2228F·····GREASE COVER (LHS)
34	·····SCREW
35	·····SCREW
36	2251FHOOK BASE RETAINING FINGER
37	SCREW FOR H36
38	2231FSEWING HOOK AND BASE
39	·····SCREW
40	2221FHOOK SHAFT

ROTARY COLOUR CHANGE HEAD AND TAKE UP MECHANISM(J)

```
No.
                Description
    2303F .....TAKE UP LEVER ASSY COMPLETE
1
    2349F .....TAKE UP LEVER
2
    2357F ..... CERAMIC THREAD GUIDE
    2356F .....SCREW FOR J3
    2353F ... ROLLER)
    2354F...STUD ) TAKE UP LEVER CAM FOLLOWER ASSY
7
         --- NUT )
8
    2351F .....TAKE UP LEVER SHAFT
9
10
    2352F .....TAKE UP SPINDLE BUSH
11
    2355F .....RETAINING COLLAR
         ·····GRUB SCREW
12
13
    2361F ....LOCK LEVER
    2363F .....THREADED STUD
14
15
         ·····WASHER
         .....SOCKET SCREW
16
17
    2364F .....LOCK BAR POSITIONING CLAMP
18
         ·····WASHER
19
         ······HEXAGONAL NUT
20
         ·····SCREW
    2365F .....LOCK LEVER BRACKET
21
         ······HEXAGONAL NUT
22
23
         ·····WASHER
24
         ·····HEXAGONAL NUT
25
         ·····WASHER
26
    3339F .....LOCK BAR HAND GRIP
        ·····GRUB SCREW
27
```






ROTARY COLOUR CHANGE HEAD AND TAKE UP MECHANISM (K)


(EXPLODED VIEW)

No.	Description
ł	2301F·····NEEDLE BAR ASSY
2	2302F·····PRESSER FOOT
3	2318FNEEDLE BAR SPRING (WIDE)
4	2321FNEEDLE BAR SPRING (NARROW)
5	2313FTHREADED BUSH (TURRET ASSY)
6	·············HEXAGONAL NUT
7	2391FNYLON WASHER (THIN)
8	2393FNYLON BUSH
9	2323FNEEDLE CLAMP
. 10	NEEDLE CLAMP SCREW
	AAAAA NEEDLE (ABEAIEV NEEDLE AAIDE)
11	2325FNEEDLE (SPECIFY NEEDLE GAUGE)
12	2332FUPPER BUSH
13	2331FNEEDLE BAR DRIVER SHAFT
14	2334HJNEEDLE BAR DRIVDR E
15	SOREW
16	2346FNEEDLE BAR CONNECTING LINK
17	2345FSOREW FOR K16
18	2347FNEEDLE BAR DRIVING FORK
19	2348FNEEDLE SHAFT CLAMP
20	SCREW FOR K19
21	2312FTHRUST RACE WASHER FOR K38
22	SSA-2015F(NMB)BEARING SPACER
23	GS-1528GS-1528 THRUST RACE WASHER FOR K24
24	NTB-1528THRUST RACE
25	AS-1528THRUST RACE WASHER FOR K24
26	2333FBEARING SHAFT
27	2335FTURRET POSITION BRACKET
28	······ALAN SCREW FOR K27
29	······SPRING WASHER
30	······WASHER FOR K28
31	2336FPIVOT CONNECTING STUD
32	RD4 020(NMB) ···PIVOT COUPLING
33	·············NUT FOR K31
34	WASHER FOR K31
35	3338FCOLOUR CHANGE ROD HAND GRIP
36	GRUB SCREW
37	GRUB SCREW FOR K12 AND K26
38	2311FNEEDLE BAR TURRET PLATE
00	ZOTTE ""NECDEE DAN FORMET FEATE




JUMP STITCH MECHANISM(L)

NO.	Description
1	2402FJUMP STITCH MECHANISM COMPLETE
2	2443FACTUATING LEVER
3	2444FBUSH
4	2445FGUIDE BUSH
5	A2015(NMB) ······BALL RACE
Б	2447F·····ROUND NUT
7	2446F····ROUND NUT
8	······SCREW
9	······WASHER
10	2449F·····NYLON STOP
11	2448FADJUSTABLE ECCENTRIC FOR STOP
12	······SCREW
13	······SPRING WASHER
14	······WASHER
15	2442FLEVER
16	SCREW FOR L15
17	2461FROTARY SOLENOID
18	NUT FOR L17
19	WASHER FOR L18
20	2451HJCOVER JUMP STITCH MECHANISM
21	2403F·············HEAD ISOLATOR ASSY
22	2452FCLUTCH RELEASE PIN
23	2455FISOLATOR PIN RETAINING BOLT
24	2456FSPRING FOR L21
25	2453FHEAD ISOLATOR ACTUATING PIN
26	······SCREW (SHORT)
27	······screw (LONG)
28	SOLENOID BRACKET BASE



THREAD TENSION ASSEMBLY (M)


No.	Description
1	2411HJTHREAD TENSION ASSY BRACKET
2	5118HJTHREAD BREAK POB
3	·····SCREW FOR 2
4	2406FUPPER TENSION UNIT COMPLETE
5	2407F
6	2401HJLOWER TENSION UNIT ASSEMBLED
7	2408FUPPER TENSION UNIT ASSEMBLED
8	2471FADJUSTING NUT UPPER AND LOWER
9	2436H·····THREAD TENSION SPRING
-10	2425FTHREAD TENSION DISCS
11	2416FTHREAD TENSION POST (UPPER)
12	2427F TENSION DISC PLASTIC INSULATOR (UPPER)
13	2475F TENSION DISC PLASTIC INSULATOR (LOWER)
14	2417FTHREAD TENSION POST (LOWER)
15	2481FOHECK SPRING
16	2477FTENSION SPRING HOLDER
17	GRUB SCREW
18	2431FSTOP MOTION CONTACT
19	2432FINSULATOR
20	··············SCREW
21	TOP THREAD GUIDE BAR
22	2433FTHREAD GUIDE (CERAMIC)
23	2491FSCREW FOR M21
24	SCREW FOR M1
25	2501FTHREAD END TRAP UNIT ASSY
26	2521FTHREAD END TRAP BASE PLATE
27	2520FINDIVIDUAL THREAD END TRAP COMPLETE
2 B	2525FSCREW FOR M27
29	2523F·····WASHER FOR M27
30	2524FSPRING FOR M27
31	2522F·····THREAD TRAP DISC
32	SCREW TRAP DISC
33	2502F THRED END TRAP UNIT ASSY (OLD UNIT)
34	2531FTHREAD END TRAP BASE PLATE
35	2530FINDIVIDUAL THREAD END TRAP COMPLETE
36	2526FSTAY
37	SCREW



From the library of Superior Sewing Machine & Supply LLC ${\color{blue} \bullet}$ www.supsew.com

DRIVE MOTOR AND CLUTCH COMPLETE (N


No.	Description
1	3111HJDRIVE MOTOR (3 PHASE)
	3112HJ // (1 PHASE)
2	3141HJDRIVE BELT
3	3161HJDRIVE BELT CASING (LOWER)
4	3162HJDRIVE BELT CASING (UPPER)
5	3164HJDRIVE BELT CASING SPACER STUD



From the library of Superior Sewing Machine & Supply LLC ${\color{blue} \bullet}$ www.supsew.com

DRIVE MOTOR AND CLUTCH EXPLODED VIEW (P)


```
No.
                 Description
    3145HJ .....CASING CLUTCH ASSY
1
    204J(FYH) ······FLANGE
         .....BOLT
         .....SPRING WASHER
         ·····WASHER
    3102HJ .....DRIVE SHAFT COUPLING ASSY
    3165HJ .....COUPLING RHS
    3166HJ .....COUPLING LHS
    3167HJ .....NYLON BUSH (STAR)
         .....GRUB SCREW
10
11
    3151HJ .....DRIVE SHAFT
    3153HJ .....KEYWAY FOR P11 (SHORT)
12
    3152HJ .....KEYWAY FOR P11 (LONG)
13
    3154HJ .....BUSH FOR P11
14
    3101HJ ....CLUTCH ASSY CB6
15
    3148HJ .....DRIVE GEAR (LARGE DRIVE SHAFT)
16
         ....ALAN SCREW
17
         ·····WASHER
1 B
19
    3149HJ .....BUSH
    5121HJ .....ANGLE POSITION CODER
20
   5-122HJ_....CODER COUPLING_
    3146HJ .....FLANGE FOR UPPER GEAR
22
         .....ALAN SCREWFOR P22
23
24
         .....WASHER FOR P22
25
          .....SCREW
  6902Z BEARING
2.6
    3139HJ .....BUSH (PULLEY SPINDLE)
27
    3147HJ .....FLANGED BEARING HOUSING
28
29
    3156HJ .....DRIVE GEAR (SMALL, PULLEY SPINDLE)
30
         .....ALAN SCREW
  3155HJ .....PULLEY SPINDLE
31
    3157HJ .....KEYWAY
32
    3138HJ .....KEYWAY
33
    3158HJ .....MOUNTING BLOCK LHS
34
    3159HJ .....MOUNTING BLOCK RHS
35
36
         ·····ALAN SCREW
37
         ·····WASHER
38
         ----NUT
  3131HJ .....PULLEY (UPPER, CLUTCH ASSY)
39
    3135HJ .....OUTER FLANGE (PULLEY SPINDLE)
         .....BOLT
41
    3131HJ .....MOTOR PULLEY (3PHASE 60 HZ)
42
    3122HJ ...... "
                              (3PHASE 50 HZ)
    3128HJ ....
                              (1PHASE 60 HZ)
    3129HJ ..... //
                              (1PHASE 50 HZ)
    3133HJ .....FLANGE FOR P42 (3 PHASE 60 HZ)
43
    3134HJ ..... //
                               (3 PHASE 50 HZ)
    3136HJ .....KEYWAY
                               (3 PHASE 60 HZ)
44
    3137HJ ...... //
3138HJ ..... //
                               (3 PHASE 50 HZ)
                                (1 PHASE 50/60 HZ)
    32024F .....BEARING AND SPACER ASSY
45
    3225F.....FLANGE
46
47
    NTN620 .....RQLLER BEARING
48
    3226F.....BUSH
         .....GRUB SCREW
49
    3226F....HELICAL GEAR
50
51
    3201F ..... CLUTCH ASSY INDIVIDUAL HEAD
    3221F.....CLUTCH
53
    3222F ..... CLUTCH PIN
54
    2456F ..... SPRING FOR P51
55
    2452F ..... CLUTCH PIN CAP
```



From the library of Superior Sewing Machine & Supply LLC \bullet www.supsew.com


ROTARY COLOUR CHANGE SELECTOR ASSEMBLY (R)

No.	Description
1	3313HJBASE ROTARY COLOUR CHANGE ASSY
2	3326HJROTARY SOLENOID MOUNTING
3	ALAN SCREW
4	SPRING WASHER
5	·······WASHER
6	··············HEXAGONAL NUT
7	3385HJROTARY ŞOLENOID
В	3324HJLINKAGE (LARGE)
9	3325HJLINKAGE PLATE
.10	JCIRCULAR SPRING PIN
11	3323HJTHREADED STUD
12	WASHER
13	······································
14	2361FLOCK LEVER
15	2363FTHREADED PIVOT STUD
16	······washer
17	············WASHER ALAN SCREW
18	SPRING WASHER
19	··············HEXAGONAL NUT
20	3329HJLOCK CONFIRMATION LEVER
21	ALAN SCREW
22	CRB6(NMB)UNIBALL COUPLING
23	SPRING WASHER
24	3351HJHEXAGON CONNECTING ROD
2.5	······································



ROTARY COLOUR CHANGE SELECTOR ASSEMBLY(S) (EXPLODED VIEW)


	(-:====================================
No.	Description .
1	3328HJCOLOUR CHANGE CONFIRMATION LEVER
2	············SCREW
3	3317HJBUSH
4	GRUB SCREW
5	5114HJNEEDLE POSITION SENSOR UNIT
6	3319HJBUSH
7	3316HJSPINDLE
8	3318HJBUSH
g	GRUB SCREW
. 10	3315HJCOLOUR CHANGE TURRET
	2000H)
11	3322HJGEAR (LARGE)
12	···········ALAN SCREW
13	2335FFLANGE PLATE FOR TURRET
14	2336FJOINT PIN
15	············WA SHE R
16	3361HJCLUTCH PLATE
17	···········ALAN SCREW
18	SPRING WASHER
19	······washer
20	3321HJ ······GEAR (SMALL)
21	···········GRUB SCREW
22	3381HJREDUCTION GEAR BOX
23	BOLT
24	SPRING WASHER
25	··········HEXAGON NUT
23	THE ANGON NOT



From the library of Superior Sewing Machine & Supply LLC ${\color{blue} \bullet}$ www.supsew.com


PANTOGRAPH DRIVE MOTOR ASSY AND TIMING BELT (T) (BACK/FORWARD MOVEMENT)

	•
No.	Description
1	4712HFINNED MOTOR COVER
2	4711HSTEPPING MOTOR
3	BOLT
4	WASHER
5	NUT
6	4715HJMOTOR MOUNTING
7	ALAN SCREW
8	SPRING WASHER
9	············WASHER
·10	4717HCONNECTING BUSH
10	47 1711 WAR GONNEGTING BOOK
11	ALAN SOREW
12	BOLT
13	SPRING WASHER
14	·······WASHER
15	4718HBUSH
16	4721HJTIMING BELT SPINDLE
	4722HJ//
	4723HJ //
	4724HJ //
17	4759HJPULLEY SPINDLE
1 B	4757HJEND CAP
19	4719HJBUSH
20	4752HJTOOTHED ROLLER
	ATCOLL COLLAD
21	4762HJCOLLAR
22	BOLT X3
23	······WASHER
24	SPRING WASHER
25	NUT
26	4731HJTIMING BELT COVER (RIGHT)
	4732HJ // (LEFT)
27	4735HJPANTOGRAPH TIMING BELT
28	4751HJTOOTHED ROLLER BEARING
29	4756HJWASHER
3 D	TA820(1 KO) ······BUSH
31	4738HJSPINDLE
32	4737HJ ······BRACKET
33	ALAN SCREW
34	SPRING WASHER
35	··············WASHER
36	BOLT
37	ALAN SCREW



PONTOGRAPH TIMING BELT ASSY (U) (BACK/FORWARDS MOVEMENT)


```
Description
No.
1
    4701HJ .....PANTOGRAPH TIMING BELT TRACK
    4702HJ .....FIXING PLATE (352)
2
    4704HJ ----- // (505)
3 4727 HJ FTXING BRACKET (RIGHT) - See - 9.14
    4728HJ ...... //
                             (LEFT)
S
        ·····SCREW
4
5
         ·····SCREW
    4725HJ .....TIMING BELT CLAMP (UPPER)
6
7
    4726HJ .....TIMING BELT GLAMP (LOWER)
         ·····SCREW
         .....WASHER
9
10
         .....NUT
11
         .....SCREW
         .....WASHER (SQUARE)
12
13
    4511HJ ....FRAME LIMIT MICROSWITCH
    4512HJ .....MOUNTING PLATE
14
15
         ·····wing NUT
         ·····SCREW
16
17
         .....NUT
```



From the library of Superior Sewing Machine & Supply LLC • www.supsew.com


PANTOGRAPH DRIVE MOTOR ASSY AND TIMING BELT (V) (LEFT/RIGHT MOVEMENT)

```
No.
                 Description
    4712H ....FINNED MOTOR COVER
1
2
    4711H .....STEPPING MOTOR
3
          .....BOLT
         -----WASHER
5
         .....NUT
6
    4716HJ .....MOTOR MOUNTING
    4717H ..... CONNECTING BUSH
7
         .....ALAN SCREW
         .....BOLT
9
         .....SPRING MOTOR
·10
         .....WASHER
11
12
    4767HJ .....BUSH
13
    4753HJ .....TOOTHED ROLLER
    4763HJ ......COLLAR
    4758HJ .....END CAP
15
    4729HJ .....ANGLE BRACKET
16
    4761HJ .....SPINDLE
17
18
         ······SCREW
          ----WASHER
19
20
         ···············SCREW
         .....SPRING WASHER
21
22
         ······WASHER
         .....NUT
23
    4733HJ .....TIMING BELT COVER (8,10,12head)
24
    (6,8,10head)
    4736HJ .....PANTOGRAPH TIMING BELT (V,8,10,12head)
25
                                       (V6 head)
    4739HJ ..... //
26
    4751HJ .....TOOTHED ROLLER
27
    4756HJ .....WASHER
28
    TA820(1KO) ----- BUSH
    4738HJ .....SPINDLE
29
30
    4737HJ .....BRACKET
         .....WASHER
31
32
         .....SPRING WASHER
33
         -----ALAN SCREW
         .....BOLT
34
35
         .....ALAN SCREW
    4510HJ .....PANTOGRAPH ( 6 head)
36
    4520HJ ----- //
                           ( 8 head)
                    //
    4530HJ .....
                           (10 head)
                    //
    4540HJ .....
                           (12 head)
```




PANTOGRAPH TIMING BELT ASSY (W) (LEFT/RIGHT MOVEMENT)

No.	Description
1	4701HJPANTOGRAPH TIMING BELT TRACK
	4703HJ//
2	4702HJFIXING PLATE
3	4227HJFIXING BRACKET (RIGHT) See P. P.
4	SCREW
5	······screw
6	4725HJTIMING BELT CLAMP (UPPER)
7	4726HJTIMING BELT CLAMP (LOWER)
В	······SCREW
• 8	WASHER
10	T
11	SCREW
12	·············WASHER (SQUARE)
13	4511HJFRAME LIMIT MICROSWITCH
14	4512HJMOUNTING PLATE
15	·····wing nut
16	SCREW
17	NUT




ELECTRONIC CONTROLS (X)

No.	Description
1	5110HJCONTROL PANEL
2	5112HJPCB (J2)
3	5113HJPCB (J3)
4	5120HJAUTOMAT MOTOR DRIVER
5	5115HJPCB (J1)
6	5116HJPCB (J2)
7	5117HJPCB (J3, J4)
B	5119HJPCB (J5, J6)
9	5201HJTRANSFORMER COVER
, 10	5211HJ ·····TRANSFORMER
11	5220H·····TAPE HANDLER/READER
12	5318FBRACKCT STOP/START SWITCH
13	5315FSTOP SWITCH CASING
14	5311F······STOP SWITCH 4€4
	5312F " GIHER!
15	5319FBRACKET-STOP/START BAR
15	5316HJSTOP/START BAR



UNDERTHREAD STOP MOTION (UTSM) ASSY(Y)

No.	Description
1	5410HJCONTROL BOX UNDERTHREAD STOP MOTION
2	5411F·····SENSOR UTSM
3	5401F·····AMPLIFIER CASING
4	5412FAMPLIFIER
5	5413FPROXIMITY SWITCH
6	5414FPROXIMITY SWITCH BRACKET
7	5416FPROXIMITY SWITCH PROBE
8	5417F······HEXAGON NUT
9	5418F·····HEXAGON NUT



From the library of Superior Sewing Machine & Supply LLC \bullet www.supsew.com

LIGHT FITTINGS, THREAD STAND, AND SUPPORTS (Z)

```
No.
                 Description
    7110F .... FLORESCENT LIGHT UNIT
1
2
    7114HJ .....TRUNKING
3
    7115F .....LIGHT STAND
4
         .....CHROME HEXAGON NUT
         -----SCREW
6
    7116F·····BRACKET
    7101HJ .....THREAD STAND ASSY ( 6 HEAD)
7
    7102HJ .....
                        //
                                    (8 HEAD)
    7103HJ .....
                       11
                                    (10 HEAD)
    7104HJ ....
                                    (12 HEAD)
                       11
    7121HJ .....UPPER COVER THREAD STAND
    7122HJ .....BASE THREAD STAND
9
1 D
    7124HJ .....THREAD GUIDE BAR
    2405H .....THREAD TENSION UNIT ASSY
11
    2471F ..... ADJUSTING NUT
12
13
    2435H------SPRING
    2425F....TENSION DISC
14
15
    2416F ..... THREAD STAND TENSION POST
16
    2421H --- BACKING PLATE
17
    2493F----NUT
18
    7125HJ .....THREAD STAND FRAME END PILLAR
    7126HJ -----THREAD STAND PILLAR
19
20
    7127HJ .....BRACKET AND ARMTHREAD STAND
    7128F ..... THREAD CONE PIN
21
         ······ WASHER
22
         ..... SPRING WASHER
23
24
         -----BOLT
25
         ······ WASHER
26
         ..... SPRING WASHER
         -----NUT
27
28
         ·····SCREW
         ······ SCREW
29
30
    1290H .....FOOT ASSY
31
         .....NUT
32
    1292H------BOLT
         ························HEXAGON NUT
33
34
         ······ WASHER
35
    1241H -----RUBBER FOOT
36
    1296H .....BOLT
37
         ······HEXAGON NUT
38
         ······WASHER
```