

Threading should be made without failure according to figures shown hereunder.

a) Five Threads

A -- Overlocking Needle Thread

B -- Double-chaining Needle Thread

C -- Upper Looper Thread

D -- Lower Looper Thread

E -- Double-chaining Looper Thread

