


# THREADING

When a machine is received, note that it has been threaded correctly. The simplest way to rethread it is to tie the new threads to those already in the machine and pull the new threads through, making sure that the knots will go through the looper eyes. In case the machine requires a complete rethreading, refer to Threading Diagrams Fig. 6 to 8.

For stitch type 504 and 505: 縫目形式: 504, 505用

Fig. 6



504



505

■■■■■ 伸縮性に富んだ糸の場合  
■■■■■ In case of stretchy thread like wooly