## TO THREAD THE BOBBIN CASE FOR MACHINE 68-32



Hold the bobbin between the thumb and forefinger of the right hand, as shown in Fig. 10, the thread drawing on the top from the left toward the right.

Fig. 10

With the left hand hold the bobbin case as shown in Fig. 11, the slot in the edge being near the top, and place the bobbin into it.



Fig. 11



Then pull the thread into the slot in the edge of the bobbin case as shown in Fig. 11; draw the thread under the tension spring and into the delivery eye at the end of the tension spring. (See Fig. 12).

Fig. 12

## TO REPLACE THE BOBBIN CASE IN MACHINE 68-32

After threading, take the bobbin case by the latch and place it on the center stud of the bobbin case holder, release the latch and press the bobbin case book will the latch catches the groove near the end of the stud and the positioning finger enters the slot at the top of the shuttle race. Allow about two inches of thread to hang free with which to commerce serving.

## TO THREAD THE NEEDLE

Pass the thread from the unwinder, down through the thread guide 1, Fig. 2 at the top of the machine, through the thread eyelet 2, Fig. 13



Fig. 13. Threading the Needle

in the upper end of the face plote, down under from left to right between the tension discs 3 or the front of the face plote, over the wive guide 4 above the tension discs, into the book 5 of the thread take-up spring, up and from left to right through the eye 6 in the end of the thread take-up leter, down through the wive thread guide 7 at the front of the face plote, into the thread sipper 8 near the lower end of the needle box, down and from front to back or from the long groove side through the eye 9 of the needle. Draw about two inches of thread through the eye of the needle with which to commence saving.

## From the library of: Superior Sewing Machine & Supply LLC